



CREEP-ZIT™ THREADED CONNECTOR WIRE RUNNING ROD SYSTEM

Creep-Zit™ Replacement Parts

Replacement Creep-Zit™ Male Bullnose Connectors (5 pack)

LS-81-010

CZMBN

Bullnose on one end and a male screw tip connector on the other.
Compatible with all Creep-Zit™ rods. Pack of five.



Replacement Creep-Zit™ Female Bullnose Connector (5 pack)

LS-81-020

CZFBN

Bullnose on one end and a female threaded connector on the other.
Compatible with all Creep-Zit™ rods. Pack of five.



Replacement Creep-Zit™ Bullnose Connector Pack

LS-81-300

TBCP

Three connectors that are bullnose on one end with female threaded connector on the other and three connectors that are bullnose on one end with male screw connector on the other.
Compatible with all Creep-Zit™ rods. Pack of six connectors.



Replacement Creep-Zit™ Bullnose Connector (5 pack)

LS-81-320

CZCOB

These bullnose connectors are non-threaded replacement tips that must be glued-onto rods using a strong, two part epoxy (not included).



Replacement Creep-Zit™ Female Threaded Connector

These female threaded tips must be glued-onto your rods using strong, two part epoxy (not included). Pack of five.



Replacement Creep-Zit™ Male Threaded Connector

These male threaded tips must be glued-onto your rods using strong, two part epoxy (not included). Pack of five.



Replacement Creep-Zit™ Threaded Connector Pack

Includes five male threaded connectors, five female threaded connectors, and two bullnose replacement tips. All tips must be glued-on to your rods using a strong, two part epoxy (not included). Pack of 12.



Replacement Clear Tube and Yellow End Caps

One clear plastic square tube with two soft yellow rubber end caps.

LS-81-355 CZTUBE



Videos for these products and more are available at GRI and LSDI YouTube:
https://www.youtube.com/channel/UC6DiB2CUXTktCd_xm0MB6VA